

YOUNG GALVANIZING, INC
JOB DESCRIPTION

Plant Title: Maintenance

Department: Plant wide

Job Summary:

To maintain the operation of all equipment at this facility. To fabricate new baskets, racks, chain slings and other lifting devices. To possess the ability to work at heights in excess of 50 feet. To be able to operate all cranes, vehicles and other machinery in the scope of this job. To be able to read prints and schematics.

Tools and Equipment:

Hand tools, air operated tools, electric operated tools, welder, man lifts, electrical wire, blue prints, schematics, brooms, and other repair tools.

Source of Supervision:

Maintenance Supervisor, Superintendent, or other management personnel as necessary

Working Procedures:

This position usually requires the employee to work with minimal amounts of supervision. This position usually requires the employee to work Saturdays and Sundays. Must be able to use hand tools, electric tools, and air-operated tools in the repair of machinery. Must be able to read blue prints, schematics or other drawings in order to correct problems with equipment. Must possess some electrical skills and be able to do wiring. Must possess some mechanical skills and learn how to troubleshoot equipment. Must have a working knowledge of motors. Must be able to troubleshoot and repair hi-lifts, trucks, cranes, burners and other equipment. Must be able to use propane or acetylene torches to burn steel. Must be able to weld, with either a stick welder or MIG welder. Must be able to pass an ASTM welding certification test. Must be able to determine the integrity of chain slings, baskets and racks. Must be able to work at heights in excess of 50 feet. Must possess a valid drivers license and hi-lift operator's license. Must be able to complete a daily inspection for hi-lifts and cranes. Must be able to do pipefitting work. Must be able to work in confined spaces and operate an air quality device. Must be able to work on and maintain non-production equipment (ie. Beta, zinc recovery unit). Must be able to follow instruction in regards to repairing, fabricating or maintaining without assistance. Must be able to wear a harness when working above four feet in height. Must be able to lift between zero to 50 lbs as needed and upon occasion up to 100Lbs. Must be able to stand, kneel operate hand and foot controls, bend, push, pull and twist while working. Must be able to wear the proper personal protective equipment as required (Long pants, long sleeved shirt, safety glasses, hearing protection, hard hat with a face shield, metatarsal shoes, rubber or cotton gloves, welding helmet when needed and other PPE as directed). Maintain a clean and safe work area.

Note:

The above statements reflect the general details considered necessary to describe the principle functions of the job identified, and shall not be construed as a detailed description of all the work required that may be inherent in the job.

Reviewed and Approved by:

Date _____